<u>Instructions for using the AC electric vehicle charging stations of EPBiH – Circontrol 2x22 kW brand</u>

Charging

To start the process of electric vehicle charging, park the electric vehicle on the marked spot dedicated only for electric vehicles.


First step in the charging process is to authenticate the used (RFID card*) on the RFID card reader:



After that, LED lights of the connectors (sockets) turn blue and the display shows the following messages:



Second step is to connect the cable to the vehicle and choose one of the available connectors (sockets). After that, connect the cable to the socket. The display shows the following messages:




Disconnecting from the network

First step in terminating the charging of the electric vehicle is to authenticate the user (RFID card) on the RFID card reader:



After that the LED lights on the connector (socket) turn green and the display shows the total charging process data (energy charged and time of charging)



To end the process of charging, disconnect the cable from the both ends. After that, the connector (socket) becomes available and the display shows the following messages:



Contact phone: 033 751 937

^{*} RFID card can be obtained from the reception desk/security guard house in the adjacent buildings of EPBiH distribution subsidiaries